

7 individual high pressure
lines




FIGURE 9B

7 individual valves





FIGURE 7








FIGURE 5



Actuation pattern (cross section view)





FIGURE 4

Mask for well, or
chamber, mold.

FIGURE 13



Mask for three different
tube assemblies.




FIGURE 14

Mask for well or chamber
and mask for tube
assemblies overlaid.

FIGURE 15

